


System upgrade method

Preliminary preparation:

1. A mobile phone with Android operating system
2. Download the APP through the QR code web page




3. Install APP




4. Turn on Bluetooth and positioning on your

phone




5. Click to enter the APP (Make sure the battery



ison) _____

6. Place the phone close to the positive and

negative terminals of the battery, or place it on the battery box cover.







7. Find the QR code on the battery box cover




8. Click on the APP Bluetooth connection and click to search for nearby devices. Find the corresponding number of the QR code. Click to enter the battery background.



9. Enter the battery background and click the control button below. Enter the control interface.



10. Click to get the version



11. Check whether the battery program version is JS-HW404-SW042



If the program version is

JS-HW404-SW039

JS-HW404-SW040


JS-HW404-SW041

Please quickly click the Get Version button
multiple times


, Complete the system upgrade through the
following operations

(The latest system program version is
JS-HW404-SW042)


12. If the versions are different, please quickly click the Get Version button multiple times.



13. After long clicking, a firmware update button will appear on the interface.




14. Get the latest program version by clicking the firmware update button



15. Click to download and upgrade. After the 100% upgrade is completed, the battery will beep. Then click Get Version to confirm that the

version has been updated to JS-HW404-SW042.



16. Please do not answer calls or exit the upgrade system interface during the download process. Answering a call or exiting the upgrade interface midway may cause battery upgrade failure or system paralysis. At the same time, please use an Android operating system mobile phone to upgrade. Bluetooth is relatively stable. Upgrading IP mobile phones will encounter Bluetooth disconnection.

